

HISTORIC AMERICAN ENGINEERING RECORD

HAER
ARIZ
11-PERIV,
1-

Index to Photographs

Coolidge Dam
On Gila River
Peridot vicinity
Pinal County
Arizona

HAER No. AZ-7

NOTE: The following photographs were provided, courtesy of the San Carlos Irrigation Project, Bureau of Indian Affairs, U. S. Department of the Interior, Coolidge, Arizona, photographer unknown:

- AZ-7-1 COOLIDGE DAM SITE, LOOKING SOUTH (DOWNSTREAM), c. 1927
- AZ-7-2 COOLIDGE DAM SITE, LOOKING SOUTH (DOWNSTREAM), c. 1927
- AZ-7-3 COOLIDGE DAM SITE, LOOKING NORTH (UPSTREAM), June 5, 1927
- AZ-7-4 CONSTRUCTION DAM LOCATED EAST OF DAM SITE, c. 1927
- AZ-7-5 CONSTRUCTION DAM, SHOWING EMPLOYEE HOUSING AT LEFT AND ADMINISTRATIVE OFFICES AT CENTER AND RIGHT, c. 1927
- AZ-7-6 CONSTRUCTION CAMP, WITH EMPLOYEE HOUSING IN FOREGROUND AND LEFT, ADMINISTRATIVE OFFICES IN BACKGROUND CENTER, December 1, 1927
- AZ-7-7 CONSTRUCTION CAMP, SHOWING VARIOUS SHOPS, c. 1927
- AZ-7-8 CONSTRUCTION SHOPS, WITH MIXING PLANT AT CENTER, December 1, 1927
- AZ-7-9 PRINCIPLE INDIVIDUALS INVOLVED IN THE CONSTRUCTION OF COOLIDGE DAM. NAMES LISTED ON IMAGE, October 7, 1928
- AZ-7-10 VIEW OF INITIAL CONSTRUCTION EFFORTS, SHOWING ROAD WORK. GRAVEL PLANT AND TRAMWAY ARE VISIBLE DOWNSTREAM, c. 1927
- AZ-7-11 VIEW OF BEDROCK EXPOSED UNDER EAST BUTTRESS, November 26, 1927
- AZ-7-12 VIEW OF CONSTRUCTION SITE, LOOKING UPSTREAM, SHOWING RIVER DIVERSION WORKS AT RIGHT, CONCRETE-PLACING TOWER AND CABLEWAYS, December 1927
- AZ-7-13 VIEW OF EXCAVATION OF SPILLWAY CHANNEL, December 1927
- AZ-7-14 VIEW OF DAM SITE, LOOKING SOUTH (DOWNSTREAM). MIXING PLANT IS VISIBLE AT RIGHT, COFFER DAM IS UPSTREAM OF PLACING TOWER. EAST DOME IS VISIBLE AT LEFT OF TOWER, c. 1927

Coolidge Dam
HAER No. AZ-7
Index to Photographs
(Page 3)

- AZ-7-31 VIEW OF DOWNSTREAM FACE WITH POWER HOUSE AND ROADWAY UNDER CONSTRUCTION, October 1928
- AZ-7-32 VIEW, LOOKING EAST, AT ROADWAY OVER DAM NEARING COMPLETION. WEST INTAKE TOWER IS VISIBLE AT FAR LEFT, November 1, 1928
- AZ-7-33 VIEW OF POWER HOUSE BASE WITH GENERATOR OPENINGS, c. 1928
- AZ-7-34 DOWNSTREAM VIEW OF COOLIDGE DAM COMPLETED. POWER HOUSE, INTAKE TOWERS, WEST SPILLWAY CHANNEL AND DECORATIVE EAGLES ALL CLEARLY VISIBLE, c. 1928
- AZ-7-35 INTERIOR VIEW OF POWER HOUSE, SHOWING GENERATORS, c. 1928
- AZ-7-36 VIEW OF COOLIDGE DAM WITH WEST ABUTMENT, c. 1928
- AZ-7-37 VIEW OF UPSTREAM FACE OF COOLIDGE DAM, c. 1928
- AZ-7-38 VIEW OF BOY SCOUTS SERVING GUESTS ATOP COOLIDGE DAM DURING DEDICATION CEREMONIES, March 4, 1930

NOTE: The following photographs were taken by Mark Durben, photographer, in 1984, courtesy of the Salt River Project Archives:

- AZ-7-39 VIEW OF DOWNSTREAM FACE OF COOLIDGE DAM
- AZ-7-40 CLOSE-UP VIEW OF DOWNSTREAM FACE, SHOWING POWER HOUSE
- AZ-7-41 VIEW OF UPSTREAM FACE OF COOLIDGE DAM
- AZ-7-42 VIEW OF COOLIDGE RESERVOIR
- AZ-7-43 VIEW OF UPSTREAM FACE OF COOLIDGE DAM, SHOWING INTAKE TOWERS, BRIDGES AND DOMES
- AZ-7-44 VIEW OF EAST SPILLWAY GATES. GATES ARE DOWN AND INOPERATIVE DUE TO A CONCRETE AND AGGREGATE REACTION
- AZ-7-45 INTERIOR VIEW OF POWER HOUSE FROM WEST END
- AZ-7-46 INTERIOR VIEW OF POWER HOUSE FROM EAST END. CRANE IS VISIBLE IN BACKGROUND
- AZ-7-47 VIEW OF POWER HOUSE CRANE
- AZ-7-48 CLOSE-UP VIEW OF CRANE MACHINERY

Coolidge Dam
HAER No. AZ-7
Index to Photographs
(Page 2)

- AZ-7-15 VIEW OF GRAVEL PLANT, WEST SIDE OF RIVER AND DOWNSTREAM OF DAM SITE WITH EMPLOYEE HOUSING AT RIGHT. TRAMWAY BUCKETS ARE CLEARLY VISIBLE, November 1, 1927
- AZ-7-16 OVERVIEW OF GRAVEL PLANT, c. 1927
- AZ-7-17 DETAILED VIEW OF CONCRETE PLACING TOWER WITH CHUTE LINES, BOOMS AND COUNTER BALANCES, December 1, 1927
- AZ-7-18 VIEW OF UPSTREAM FACE OF DAM, ALL THREE DOMES VISIBLE WITH EAST BUTTRESS. RIVER DIVERSION IS THROUGH THE EAST DOME, c. 1928
- AZ-7-19 CLOSE-UP VIEW OF RIVER DIVERSION, UPSTREAM FACE OF EAST DOME AND BUTTRESS, January 1, 1928
- AZ-7-20 VIEW LOOKING EAST FROM WEST SPILLWAY. CROSS SECTIONAL VIEW OF DOMES, PENSTOCK OUTLET VISIBLE IN CENTRAL DOME, January 17, 1928
- AZ-7-21 VIEW OF DOWNSTREAM FACE OF COOLIDGE DAM, WITH RIVER DIVERSION AT RIGHT, March 1928
- AZ-7-22 VIEW OF DAM FROM WEST SPILLWAY, May 1928
- AZ-7-23 VIEW OF UPSTREAM FACE OF DAM. TWIN INTAKE TOWERS VISIBLE AT EITHER SIDE OF CENTRAL DOME, May 3, 1928
- AZ-7-24 VIEW OF DOWNSTREAM FACE OF DAM WITH EXCELLENT VIEW OF PLACING TOWER. POWER HOUSE OUTLETS ARE VISIBLE AT BASE OF CENTRAL DOME, c. 1928
- AZ-7-25 VIEW OF UPSTREAM FACE OF DAM NEARLY COMPLETE WITH CONSTRUCTION SHOPS, c. 1928
- AZ-7-26 CLOSE-UP VIEW OF UPSTREAM FACE OF DOMES WITH TOWER INTAKES, July 1, 1928
- AZ-7-27 VIEW OF DOWNSTREAM FACE WITH WEST SPILLWAY BRIDGE UNDER CONSTRUCTION AT LEFT, August 1928
- AZ-7-28 UPSTREAM VIEW OF DOMES AFTER STRIPPING. INTAKES, SPILLWAYS AND RIVER DIVERSION WORKS ALL VISIBLE, October 13, 1928
- AZ-7-29 VIEW OF WEST SPILLWAY BRIDGE UNDER CONSTRUCTION, September 1, 1928
- AZ-7-30 VIEW OF DOWNSTREAM FACE WITH EAST SPILLWAY CHANNEL UNDER CONSTRUCTION, September 1928

Coolidge Dam
HAER No. AZ-7
Index to Photographs
(Page 4)

- AZ-7-49 VIEW OF EAST TURBINE
- AZ-7-50 VIEW OF POWER HOUSE CONTROL ROOM FROM WEST END
- AZ-7-51 VIEW OF WEST PANEL CONTROL BOARD
- AZ-7-52 VIEW OF EAST PANEL CONTROL BOARD
- AZ-7-53 VIEW OF CENTRAL PANEL CONTROL BOARD
- AZ-7-54 VIEW OF COOLIDGE DAM SWITCHYARD LOCATED BEHIND POWER HOUSE IN
CENTRAL DOME. TRACK USED TO MANIPULATE TRANSFORMERS IS VISIBLE
- AZ-7-55 VIEW OF SWITCHYARD, FACING POWER PLANT

NOTE: The following are photographs of drawings of the Coolidge Dam, courtesy of the San Carlos Project, U. S. Indian Service, Department of the Interior:

- AZ-7-56 DIMENSION DRAWINGS OF DOME AND BUTTRESS
- AZ-7-57 MULTIPLE DOME TYPE, SHOWING FORMS AND FALSE WORK CONSTRUCTION
- AZ-7-58 PORTION OF EAST SPILLWAY AND DOME, SHOWING ELEVATIONS FOR EXCAVATION
- AZ-7-59 PORTION OF WEST SPILLWAY AND DOME, SHOWING ELEVATIONS FOR EXCAVATION
- AZ-7-60 4-INCH DRAINS, EAST SPILLWAY
- AZ-7-61 DETAILS OF 6-INCH DRAIN PIPE, EAST PIER, WEST SPILLWAY
- AZ-7-62 DETAILS OF TUNNEL THROUGH WEST BUTTRESS
- AZ-7-63 DETAILS OF DISCHARGE TUNNEL THROUGH WEST MIDDLE PIER, WEST SPILLWAY
- AZ-7-64 DETAILS OF DISCHARGE TUNNEL THROUGH WEST MIDDLE PIER, EAST SPILLWAY
- AZ-7-65 DETAILS OF DISCHARGE TUNNEL THROUGH EAST MIDDLE PIER, EAST SPILLWAY
- AZ-7-66 DETAILS OF DISCHARGE TUNNEL THROUGH EAST MIDDLE PIER, WEST SPILLWAY
- AZ-7-67 DETAIL OF STAIRWAY TO LAVATORY IN WEST BUTTRESS
- AZ-7-68 DETAILS OF WALLS OVER WEST BABY BUTTRESS AND EAST PIER, WEST
SPILLWAY

AZ-7-69	STEEL REINFORCEMENT IN WEST BUTTRESS
AZ-7-70	LOCATION AND DETAILS OF CONSTRUCTION JOINTS IN EAST BUTTRESS
AZ-7-71	STEEL LAYOUT IN ROADWAY FLOOR SLAB OVER A AND B BUTTRESSES
AZ-7-72	STRESSES IN THE BUTTRESSES DUE TO DEAD LOAD AND WATER PRESSURE
AZ-7-73	DETAILS OF EAST PIER, WEST SPILLWAY
AZ-7-74	SECTION THROUGH SPILLWAY BETWEEN PIERS
AZ-7-75	DETAILS OF WEST PIER, EAST SPILLWAY
AZ-7-76	PIER DETAILS
AZ-7-77	PIER DETAILS
AZ-7-78	PIER DETAILS
AZ-7-79	PIER DETAILS
AZ-7-80	HORIZONTAL SECTION AT ELEVATION 2300
AZ-7-81	HORIZONTAL SECTION AT ELEVATION 2400
AZ-7-82	SECTION OF DAM SHOWING LOCATION OF GROUT
AZ-7-83	SECTION SHOWING STEEL REINFORCEMENT IN LOWER PORTION OF EAST DOME
AZ-7-84	STEEL IN UPPER PORTION OF OUTLET TOWER
AZ-7-85	STEEL REINFORCEMENT
AZ-7-86	STEEL IN UPPER PORTION OF DOMES
AZ-7-87	DETAILS OF SPILLWAY WALLS
AZ-7-88	ELEVATIONS FOR EXCAVATION ON WEST SPILLWAY
AZ-7-89	ELEVATIONS FOR EXCAVATION ON EAST SPILLWAY
AZ-7-90	WEST SPILLWAY PROFILES
AZ-7-91	EAST SPILLWAY PROFILES

Coolidge Dam
HAER No. AZ-7
Index to Photographs
(Page 6)

AZ-7-92 SPILLWAY BRIDGE DETAILS

AZ-7-93 FINISHED CONCRETE GRADES ON PORTION OF WEST SPILLWAY

AZ-7-94 FINISHED CONCRETE GRADES, EAST SPILLWAY

AZ-7-95 RETAINING WALL DETAILS, OUTSIDE LINE, WEST SPILLWAY

AZ-7-96 DETAILS FOR PORTION OF WEST SPILLWAY WALL

AZ-7-97 DETAILS FOR PORTION OF WEST SPILLWAY WALL

AZ-7-98 WEST SPILLWAY DETAILS

AZ-7-99 FINISHED CONCRETE GRADES ON PORTION OF WEST SPILLWAY

AZ-7-100 INSIDE WALL DETAILS, WEST SPILLWAY

AZ-7-101 DETAILS OF PORTION OF WEST SPILLWAY

AZ-7-102 PIPE CONNECTIONS FOR DRAINS FROM SPILLWAY OPERATING CHAMBERS

AZ-7-103 4-INCH CONCRETE DRAINS UNDER WEST SPILLWAY

AZ-7-104 DOWNSTREAM BAY, DETAILS OF PARAPET WALLS AND CORBELS

AZ-7-105 UPSTREAM BAY, DETAILS OF PARAPET WALLS AND CORBELS

AZ-7-106 LAYOUT OF PIPE RAILING ON EAST PIER, WEST SPILLWAY AND WEST PIER,
EAST SPILLWAY

AZ-7-107 OUTLET TOWER DETAILS

AZ-7-108 BRIDGE TO OUTLET TOWER

AZ-7-109 PARAPET WALL DETAILS

AZ-7-110 DETAILS OF WALLS OVER DOMES

AZ-7-111 DETAILS OF WALLS OVER EAST BUTTRESS

AZ-7-112 DETAILS OF WALLS OVER WEST BUTTRESS

AZ-7-113 WEST SPILLWAY BRIDGE, PARAPET WALL DETAILS

AZ-7-114 STEEL LAYOUT IN ROADWAY FLOOR SLAB OVER DOMES AND BUTTRESSES

Coolidge Dam
HAER No. AZ-7
Index to Photographs
(Page 7)

AZ-7-115 ROADWAY SLAB ELEVATIONS
AZ-7-116 ROADWAY SLAB ELEVATIONS
AZ-7-117 DETAIL OF UPPER PART OF BAY
AZ-7-118 COUNTERFORT WALL DETAILS, ROAD TO POWER HOUSE
AZ-7-119 RETAINING WALL AND FLOOR SYSTEM ROAD TO POWER HOUSE
AZ-7-120 DETAILS OF FLOOR SYSTEM, ROAD TO POWER HOUSE
AZ-7-121 DETAIL OF POWER HOUSE ABOVE ELEVATION 2330, SHEET 1
AZ-7-122 DETAIL OF POWER HOUSE ABOVE ELEVATION 2330, SHEET 2
AZ-7-123 POWER HOUSE FOUNDATION PLAN AND DETAILS
AZ-7-124 POWER HOUSE FOUNDATION DETAILS
AZ-7-125 POWER HOUSE FOOTINGS
AZ-7-126 DETAIL OF ROADWAY IN POWER HOUSE
AZ-7-127 POWER HOUSE EQUIPMENT, GENERAL LAYOUT
AZ-7-128 GENERATOR FOUNDATION DETAILS
AZ-7-129 GENERATOR FOUNDATION DETAILS

HISTORIC AMERICAN ENGINEERING RECORD

HAER
ARIZ,
11-PERIV,
1-

Index to Photographs

Addendum to:

Coolidge Dam
San Carlos Apache Indian Reservation
On the Gila River
Peridot Vicinity
Pinal County
Arizona

HAER No. AZ-7
(Page 8)

NOTE: Photographs were taken by Bob Knotts, photographer, January and June 1991

Photographs No. AZ-7-1 through AZ-7-129 were previously submitted to the Library of Congress.

AZ-7-130	VIEW OF COOLIDGE DAM, FACING SOUTH, SHOWING THE THREE-ARCHED DOMES OF THE INTAKE TOWERS (June 1991)
AZ-7-131	CLOSE-UP VIEW OF RIGHT INTAKE TOWER, FACING EAST (January 1991)
AZ-7-132	CLOSE-UP VIEW OF LEFT INTAKE TOWER WITH RIGHT INTAKE TOWER IN BACKGROUND, FACING WEST (January 1991)
AZ-7-133	VIEW OF RIGHT (WEST) SPILLWAY GATES, FACING WEST. GATES ARE DOWN AND INOPERATIVE. (June 1991)
AZ-7-134	VIEW OF LEFT (EAST) SPILLWAY GATES, LOOKING EAST. GATES ARE DOWN AND INOPERATIVE. (June 1991)
AZ-7-135	VIEW LOOKING SOUTH (DOWNSTREAM) DOWN THE SPILLWAY, SHOWING TOP OF RIGHT SPILLWAY (January 1991)
AZ-7-136	VIEW, TAKEN FROM BASE OF SPILLWAY, LOOKING UP RIGHT (WEST) SPILLWAY, FACING NORTHWEST (January 1991)
AZ-7-137	VIEW, TAKEN FROM WEST SIDE OF GILA RIVER, LOOKING UP LEFT (EAST) SPILLWAY, FACING NORTHEAST (January 1991)
AZ-7-138	VIEW OF WESTERN APPROACH TO THE DAM, SHOWING DECORATIVE LAMP PYLONS FLANKING THE ENTRANCE AND THE PARAPET WALLS ON TOP OF DAM, LOOKING SOUTH (January 1991)

- AZ-7-139 VIEW OF THE COMPLETE LEFT (EAST) DECORATIVE LAMP PYLON AND PORTION OF PARAPET WALL ON THE WESTERN APPROACH TO THE DAM, LOOKING EAST (January 1991)
- AZ-7-140 CLOSE-UP VIEW SHOWING THE LOWER PART OF THE RIGHT (WEST) DECORATIVE LAMP PYLON ON THE WESTERN APPROACH TO THE DAM, LOOKING SOUTHEAST (June 1991)
- AZ-7-141 VIEW OF LAMP FIXTURE ON TOP OF RIGHT (WEST) DECORATIVE LAMP PYLON ON THE WESTERN APPROACH TO THE DAM, FACING NORTHWEST (June 1991)
- AZ-7-142 CLOSE-UP VIEW OF LAMP FIXTURE ON TOP OF RIGHT (WEST) DECORATIVE LAMP PYLON ON THE WESTERN APPROACH TO THE DAM, FACING WEST (June 1991)
- AZ-7-143 VIEW OF PARAPET WALL WITH ONE OF THE LAMP COLUMNS (WITH LAMP REMOVED). PARAPET WALL FLANKS ROAD ACROSS TOP OF DAM. THIS SECTION OF PARAPET WALL IS ON THE SOUTH SIDE OF THE DAM, LOOKING SOUTHWEST (January 1991)
- AZ-7-144 VIEW SHOWING A SECTION OF THE PARAPET WALL ON SOUTH SIDE OF THE TOP OF THE DAM, LOOKING WEST (January 1991)
- AZ-7-145 DETAIL VIEW OF SECTION OF PARAPET WALL, SHOWING DECORATIVE CONCRETE WORK, LOOKING WEST (January 1991)
- AZ-7-146 DETAIL VIEW, LOOKING STRAIGHT ON, OF CAST IRON LAMP STANDARD. THIS AND OTHER LAMP STANDARDS WERE REMOVED FROM THE LAMP COLUMNS ON THE PARAPET WALLS DURING WORLD WAR II AND STORED INSIDE THE DAM (January 1991)
- AZ-7-147 DETAIL VIEW OF CAST IRON LAMP STANDARD, VIEWED AT AN ANGLE, ONE-FOOT RULE INCLUDED FOR SCALE (January 1991)
- AZ-7-148 VIEW OF DOWNSTREAM FACE OF COOLIDGE DAM, SHOWING THE CONCRETE EAGLES LOCATED ON THE SIDES OF THE TWO TURNOUTS. THE WESTERN TURNOUT IS ON THE LEFT, AND THE EASTERN TURNOUT IS ON THE RIGHT (June 1991)

Addendum to:

Coolidge Dam
HAER No. AZ-7
Index to Photographs
(Page 10)

The following views are 4" x 5" enlargements from 2-1/4" x 2-1/4" negatives.

AZ-7-149	VIEW OF THE WESTERN TURNOUT AND EAGLE, TAKEN FROM THE DOWNSTREAM SIDE OF DAM (January 1991)
AZ-7-150	VIEW OF THE EASTERN TURNOUT AND EAGLE, TAKEN FROM THE DOWNSTREAM SIDE OF DAM (January 1991)
AZ-7-151	VIEW SHOWING THE LEFT SIDE OF THE EAGLE LOCATED ON THE WESTERN TURNOUT (January 1991)
AZ-7-152	VIEW SHOWING THE RIGHT SIDE OF THE EAGLE LOCATED ON THE EASTERN TURNOUT (January 1991)
AZ-7-153	CLOSE-UP VIEW OF THE LEFT SIDE OF THE EAGLE LOCATED ON THE EASTERN TURNOUT (January 1991)
AZ-7-154	VIEW LOOKING SOUTH FROM THE TOP OF DAM, SHOWING THE DOWNSTREAM CONTEXT OF THE DAM (June 1991) (From 4x5 negative)